

Barr et al. Filed 10/3\_/2001 Method To Correct For Malfunctioning Ink Ejection Elements In A Single Pass Print Mode Sheet 1 of 6 10014029-1



Barr et al. Filed 10/3\_/2001 Method To Correct For Malfunctioning Ink Ejection Elements In A Single Pass Print Mode Sheet 2 of 6 10014029-1




at the talk that other

H. M. H. H.

#" #"# #"# #"" #"# #" #

Barr et al. Filed 10/3\_/2001 Method To Correct For Malfunctioning Ink Ejection Barr et al. Filed 10/3\_/2001 Method To Correct For Malfunctioning Ink Ejection Elements In A Single Pass Print Mode Sheet 4 of 6 10014029-1







FIG. 6



Dall Ct al. 1 1100 10/3\_/2

FIG. 5